# U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT ESI-PRP Removal - Removal Polrep



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject:

POLREP #15

**Progress** 

**ESI-PRP Removal** 

**B5YS** 

Indianapolis, IN

Latitude: 39.9128600 Longitude: -86.2423680

To:

Sue Michael, City of Indianapolis

Tom White, City of Indianapolis

Harry Atkinson, IDEM Ryan Groves, IDEM Megan Nagle, IDEM George Richotte, IDEM

Jason Doerflein, Marion County Health Department

Stephen Jones, Pike Fire Department

Linda Nachowicz, U.S. EPA Region V, ERB 2

Charles Gebien, U.S. EPA Region V John Maritote, U.S. EPA Region V Janet Pope, U.S. EPA Region V

Debbie Keating, U.S. EPA Region V, ESS Karen Kirchner, U.S. EPA Region V, LCD Kendall Moore, U.S. EPA Region V, LCD Susan Perdomo, U.S. EPA Region V, ORC Gary Prichard, U.S. EPA Region V, ORC John Steketee, U.S. EPA Region V, ORC Carol Staniec, U.S. EPA Region V, Water

Kim Cussen, United Water

Nola Hicks, U.S. EPA Region V, ORC

Mark Johnson, ATSDR

Robert Darnell, U.S. Department of Justice

Stan Rigney, IDEM Randy Braun, IDEM USCG NRC, NRC

David Chung, U.S. EPA HQ

Jeff Kelley, U.S. EPA Maupin Natalie, IDEM

Eric Kaufman, Marion County Health Department

Jason Sewell, IDEM

Carol Ropski, U.S. EPA Region V, ESS

Jason Ravenscroft, Marion County Health Department



Sherry Fielding, U.S. EPA HQ

Dan Sparks, USFWS Ed Karecki, USFWS Bob Masbaum, POTW

Kristen Heitman, Providence Wildlife Michael Massonne, City of Indianapolis

From:

Verneta Simon & Anita L. Boseman, On-Scene Coordinators

Date:

8/4/2011

Reporting Period: August 1, 2011 - August 5, 2011

#### 1. Introduction

#### 1.1 Background

Site Number:

B5YS

Contract Number:

D.O. Number:

CEDCLA

Action Memo Date:

9/30/2010

Response Authority: CERCLA

CLA Response Type:

PRP Oversight

Response Lead:

**NPL Status:** 

PRP

**Incident Category: Operable Unit:** 

Removal Action

**Mobilization Date:** 

Non NPL 4/6/2011

Start Date:

4/6/2011

Demob Date:

**Completion Date:** 

**CERCLIS ID:** 

INN0051050501

RCRIS ID:

**ERNS No.:** 

**State Notification:** 

FPN#:

Reimbursable Account #:

#### 1.1.1 Incident Category

Bankrupt Commercial Used Oils Facility

#### 1.1.2 Site Description

See POLREP 1

#### 1.1.2.1 Location

4910 West 86th Street, Indianapolis, Indiana 46268

#### 2. Current Activities

#### 2.1 Operations Section

2.1.1 Narrative See POLREP 1

#### 2.1.2 Response Actions to Date

On August 1, 2011, Midwest hauled off 3 loads (22,500 gal) of oily water from the off-spec storage tanks 42 & 45 and the access pit to United Waste Water Inc.'s facility in Cincinnati, OH.

- A precipitation event occured overnight.
- Midwest continued to remove sludge from the DAF tanks. Sludge and waste water was moved to the vac tanks on the north side of
  the cite.
- Midwest began removing sludge from API tank 2. Sludge and waste water was moved to the vac tanks on the north side of the site.
  - START conducted air monitoring around the perimeter of the bunker tanks and work areas.

Janet Pope, Community Involvement Coordinator (CIC), and OSC Simon attended the community meeting. During this
meeting, they received a copy of the Judge's Motion which is contained in the documents section.

On August 2, 2011, Midwest hauled off 4 loads (22,500 gal) of oily water from the off-spec storage tank 41 and the access pit to United Waste Water Inc.'s facility in Cincinnati, OH.

- Midwest continued to remove sludge from the DAF separators. Sludge and waste water was moved to the vac tanks on the north side of the site.
- Midwest continued to remove sludge from API tank 2. Sludge and waste water was moved to the vac tanks on the north side
  of the site.
- Midwest finalized disposal options for drums and totes and will begin transportation offsite later in the week.
- 2 new sludge vacuum boxes were delivered to the site for solids bulking.
- Midwest began removing sludge from the unloading pit (pit just south of the DAF tanks).
  - O Confined space entry was performed to begin cleaning of the pit.
- START conducted air monitoring around the perimeter of the bunker tanks and work areas.

On August 3, 2011, Midwest hauled off 5 loads (27,150 gal) of oily water from the off-spec storage tank 42 and the access pit to United Waste Water Inc.'s facility in Cincinnati, OH and Clean Water in Dayton, OH.

- · There was no observed precipitation in the rain gauge this morning.
- Midwest continued to remove sludge from the DAF separator (52SP01A). Sludge and waste water was moved to the vacuum boxes on the north side of the site.
- Midwest removed 600 gallons of oily water from off spec storage tank 42.
- Midwest removed 20,000 gallons of oily water from the concrete access pit.
- · Trihydro conducted an emergency drill.
- Trihydro received analytical report for samples collected from the bunker tanks.
- Midwest continued to remove sludge from the unloading pit and began power washing (pit just south of the DAF tanks).
  - O Confined space entry was performed.
- START conducted air monitoring around the perimeter of the site and work areas.

On August 4, 2011, Midwest hauled off 4 loads (27,050 gal) of oily water from the access pit to United Waste Water Inc.'s facility in Cincinnati, OH and 1 load (3,885 gal) of totes and drums containing haz-waste to EEI in Columbus, OH.

- There was no observed precipitation in the rain gauge this morning.
- Midwest continued removing sludge from the DAF separator (52SP01A). Most of the separator was power-washed before the
  vac truck lost suction. Any sludge and waste water was moved to the vacuum boxes on the north side of the site.
- 2 new sludge vacuum boxes were delivered to the site for solids bulking.
- Trihydro received analytical reports for air samples collected on 7/22/11 and 7/29/11.
  - O The analytical results indicate that the only compound detected was H2S.
- Midwest continued to remove sludge from the unloading pit and finished power-washing.
  - O Discussion on whether the pit is clean still needs to happen.
  - O There was also discussion on whether the grates on the top should be power washed or disposed of as haz-waste. Further washing of the top could further spread the waste.
  - O Confined space entry was performed.
- Michael Tragesser from United Waste Water, Inc. was on site to discuss the west million gallon tank and how much oil versus water exists. It was concluded that pumping from the access pit was still the best idea.
- Approximately half of the drums and totes were hauled off Site by Midwest to Environmental Enterprises Incorporated in Columbus, OH.
- Midwest collected 7 samples from the 10 vac tanks.
  - O Samples will be sent to ASI to be profiled.
  - O 3 of the tanks are sampled as a composite because of their similarities in content.
- Midwest collected 1 composite sample from the 4 sludge tanks in the solids building.
- START conducted air monitoring around the perimeter of the site and work areas.

On August 5, 2011, Midwest hauled off 5 loads (26,550 gal) of oily water from the access and separator pits to United Waste Water Inc.'s facility in Cincinnati, OH.

- · There was no observed precipitation in the rain gauge this morning.
- · Midwest removed storm water/oily water from separator pit.
- · Midwest power-washed API separator.
- Midwest prepared site for a possible rain event.
- START conducted air monitoring around the perimeter of the bunker tanks and work areas.

## 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs) $\ensuremath{\text{N/A}}$

#### 2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal
Oily Water	Liquid	2,521,993 gallons		х	,
Stormwater	Liquid	424,956 gallons		X	
Tank 51 Containment	Liquid	335,120 gallons		Х	
Totes and Drums	Liquid	3,885 gallons		X	

#### 2.2 Planning Section

#### 2.2.1 Anticipated Activities

• Approved Work Plan

#### 2.2.1.1 Planned Response Activities

None

#### **2.2.1.2 Next Steps**

US EPA will provide oversight of PRP Group removal activities.

Use decontaminated Tank 6 for storm water storage.

#### **2.2.2** Issues

Starting in Mid-July, the weather became very hot and humid, and special care was taken to make sure that people working outside are well hydrated and taking adequate breaks.

Groundwater infiltration is suspected in the sanitary sewer system on Site. Trihydro is investigating potential options for mitigating infiltration.

Standing water has been observed in several locations around the site. Warmer weather can lead to mosquito breeding in standing water. EPA has requested that Trihydro address all standing water on site as soon as possible.

Ongoing management of wildlife at the site due to nearby ecosystems.

In previous POLREPs an incorrect name was used when referring to the oily water disposal facility. The correct name should be United Waste Water, Inc. not United Water.

#### 2.3 Logistics Section

Not applicable.

#### 2.4 Finance Section

#### 2.4.1 Narrative

Not applicable.

#### 2.5 Safety Officer

Not applicable.

#### 2.6 Liaison Officer

Not applicable.

#### 2.7 Information Officer

#### 2.7.1 Public Information Officer

#### 2.7.2 Community Involvement Coordinator

A date has not been selected for the next community meeting.

#### 3. Participating Entities

#### 3.1 Unified Command

Indiana Department of Environmental Management Indianapolis Department of Public Works Pike Township Fire Department City of Indianapolis

#### 3.2 Cooperating and Assisting Agencies

Marion County Health Department

#### 4. Personnel On Site

U.S. EPA START Contractor

#### 5. Definition of Terms

ASAOC – Administrative Settlement Agreement on Consent ERRS - Emergency and Rapid Response Services IDEM - Indiana Department of Environmental Management OSC - On-Scene Coordinator POLREP - Pollution Report PRP - Potentially Responsible Party RCRA - Resource Conservation and Recovery Act START - Superfund Technical Assessment and Response Team U.S. EPA – United States Environmental Protection Agency

#### 6. Additional sources of information

#### 6.1 Internet location of additional information/reports


For additional information, please refer to the US EPA lead removal action website at www.epaosc.org/esi

## **6.2 Reporting Schedule**

The next POLREP will be submitted at a date to be determined.

### 7. Situational Reference Materials

For additional information, please refer to the documents section at www.epaosc.org/esi





181051

For Routal into Cali: 888-703-8265

**44** 1

08/04/2011